

TYP OOP 2.7, CERTIFIKAČNÍ KATEGORIE I.

Návod na použití, skladování a ošetřování lyžařských brýlí

Použití:

Brýle nasadíte na obličej a gumový pásek natáhněte přes lyžařskou přilbu. Ujistěte se že vám brýle správně sedí na očích. Pro utáhnutí či povolení brýlí na přilbě použijte přezky na pásku.

Skladování:

Skladovat výrobek v suchých skladech, min. 1 metr od topných těles a na místech bez stálého slunečního záření.

Materiál:

TPU (termoplastický polyuretan)

Údržba:

Neperte v pračce, otřete vlhkým hadříkem.

Brýle splňují normu EN 174:2001

FORCE.BIKE

Dodavatel / Importer
KCK Cyklosport-Mode s.r.o., Bartošova 348, 765 02 Otrokovice-Kvitkovice, CZ
www.kckcyklosport.cz, www.force.cz
Země původu Taiwan / Made in Taiwan

TYPE PPE 2.7, CERTIFICATION CATEGORY I.

Instructions for use, storage and care of ski goggles

Use:

Put the eyeglasses on your face and pull the rubber strap over the ski helmet. Make sure your glasses are right in your eyes. Use the strap buckles to tighten or allow goggles on the helmet.

Storage:

Store product in dry warehouses, min. 1 meter away from heaters and in places without constant sunlight.

Material:

TPU (thermoplastic polyuretan)

Maintenance:

Do not wash the machine, wipe it with a wet cloth.

The goggles comply with EN 174: 2001 standard.

FORCE.BIKE

Dodavatel / Importer
KCK Cyklosport-Mode s.r.o., Bartošova 348, 765 02 Otrokovice-Kvitkovice, CZ
www.kckcyklosport.cz, www.force.cz
Země původu Taiwan / Made in Taiwan